

# BEST AVAILABLE COPY

## SEARCH

Class	Sub.	Date	Exmr.
409	234	2/12/03	EEC
408	239R		
	239A		
	238		
279	102		
29	447		
403	28-30		
	273		
409	232		
updated		8/5/03	EEC
updated		4/15/04	EEC
updated		11/16/04	EEC

INTERFERENCE SEARCHED			
Class	Sub.	Date	Exmr.
as above		11/22/04	EEC

## SEARCH NOTES

(List databases searched. Attach search strategy inside.)

	Date	Exmr.
FAST Text search	2/12/03	EEC
PALM Inventor & Assignee Search		
Viewed 10/238756 09/786649	2/13/03	EEC
to check Double Pat. No D.P.		
Consulted Akiko Smith, Japanese translator	4/16/04	
re JP 2-41807. She said there was no mention of the material of the spindle or of the material of the tool held by sleeve (the conical sleeve)		
409/234 X 29/447 Fig 1 B28C 5/26		

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

**BLACK BORDERS**

**IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**

**FADED TEXT OR DRAWING**

**BLURRED OR ILLEGIBLE TEXT OR DRAWING**

**SKEWED/SLANTED IMAGES**

**COLOR OR BLACK AND WHITE PHOTOGRAPHS**

**GRAY SCALE DOCUMENTS**

**LINES OR MARKS ON ORIGINAL DOCUMENT**

**REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**

**OTHER: \_\_\_\_\_**

**IMAGES ARE BEST AVAILABLE COPY.**

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.